	OFFIC	CIAL ROUTING	SLIP	•	- , .
то		D ADDRESS	DATE INITIALS		·/\ .
1	Deputy Direct	tor for Support	10 July		de
2 F			,	R L L B A	
3		PSD	LX-		•
_				·	
4 -	·				
5					
6					:
	ACTION	DIRECT REPLY DISPATCH	PREPARE REPLY RECOMMENDATION		•
	APPROVAL	FILE	RETURN	1	
	CONCURRENCE	INFORMATION	SIGNATURE]	
		ment that h	e give me		
NTI		ment that he mamo to h	assort		
	L				
	FOLD	HERE TO RETURN TO	O SENDER NO. DATE		
NTI NTI	FOLD	HERE TO RETURN TO	O SENDER		
	FOLD FROM: NAME actor of Pe	HERE TO RETURN TO E. ADDRESS AND PHONE PROPERTY OF THE PROPERT	O SENDER NO. DATE 1070 SECRET		
NTI FORM	FOLD FROM: NAME ector of Pe UNCLASSIFIE NO. 237 Use previous S:RLB:maq	HERE TO RETURN TO E. ADDRESS AND PHONE PROPERTY OF THE PROPERT	O SENDER NO. DATE 1070 SECRET	10)	
FORM DDD	FOLD FROM: NAM ector of Pe UNCLASSIFIE NO. 237 Use previous S: RLB: maq etribution:	HERE TO RETURN TO E. ADDRESS AND PHONE PROPERTY OF THE PROPERT	O SENDER NO. DATE F OF IJL 1970 SECRET		

For Release 2003/04/29 : CIA-RDP8	4-0078
T.Mr.	
·	
	s
also looking met	the
light problem as	
result of Dais State	٨
of the agency much	
filming	
1 0 JUL 1970	

ے درس

· 9 JUL 1970

MEMORANDUM FOR: Deputy Director for Support

Bob:

You asked me to give you a note regarding the lighting problem in the auditorium. Last year when we were preparing for the September Awards Carenony I discussed this with He told me that there is available on the market a quarts/halogen light which would fit in the six receptacles in the top of the auditorium, probably pulling little more current than the lights presently installed and having a low heat factor. If I remember commectly, I mentioned this to I am not sure, however, I also think nothing was done because no individual was charged with the sespensibility for insuring that we had proper lighting for color photography and there were other demands on people's attentions. I would note also that, through what I consider a pretty serious engineering design oversight, there is no simple way to get to any of the light fixtures in the auditorium, even for simply replacing the lights to say nothing of installing new gear. I understand, in fact, that it is a fairly expensive process to see up what I call "tinker toy" scaffolding, which once erected has to be taken down and reassembled to get at different light fixtures. I am going to look into some means of employing the suggestion system to find an ingenious solution to that problem. I will be back to you on that.

Sig. 22

Robert S. Wattles Director of Personnel

Distribution:

0&7 - Addressee 1 - D/Pers Chrono

Pers/RSWattles:mtw (9 Jul 70)

Approvent from Release v2003/04/29 CIA-RDP84-00780R003800200017-3

STAT